



www.vscq.com.au

## VEHICLE INSPECTION REPORT

**Customer** Sellyourcarfast.com.au

**Location:**

**TMR INSPECTORS #**

18107

**Inspector:** M Gambin

**RTA INSPECTORS #**

A68816

**Make:**

Holden

**Model:**

VE Commodore

**Badged:**

SV6 Series II

**Registration**

**Number**

\*\*\* \*\*

**State**

QLD

**Expiry**

29/6/2016

**Body Colour:**

White

**Aust. Compliance:**

30/09/2011

**Build Date:**

09/11

**Odometer KM:**

50 419

**Vin Number:**

6GI\*\*\*\*\*256

**Engine Number:**

LF\*\*\*\*\*1

**Number of Cylinders:**

6

**Number of Doors:**

4

**Engine Type:** UNLEADED

**Transmission Type:** Manual – 6 Speed

The onus of the vehicles authenticity/verification is solely the responsibility of the purchaser. VIN and engine numbers can be checked for tampering, however, not guaranteed. Engine number will only be recorded from the engine if clearly visible, otherwise copied from registration records if available. Inspection and assessment has been by visual and noise appreciation only and no adjustment have been made nor components seen or it does not appear during the inspection. It is the opinion of our experienced inspectors that the items are in the condition indicated on this report.

Should there be a concern with the accuracy of this report contact Vehicle Safety Certificates Queensland prior to any work being carried out. THIS REPORT IS NOT A WARRANTY OR GUARANTEE, IT IS ONLY INTENDED FOR THE PERSONS NAMED ABOVE AND IS NOT TO BE RELIED UPON BY ANY OTHER PERSONS OR PURPOSE.

WHAT WE DON'T CHECK – Fuel and oil consumption, timing belts, alarm/security system, trip meters/computers, navigation equipment/GPS, operation of TV, cassette or compact disc player, automatic switching of wipers and lights, body work water leaks. We only inspect the components on the report checklist, further inspection may be recommended for any concern found.

# Engine and Engine Bay

S = Satisfactory/Consistent with Mileage

N = Needs Service/Repair

	S	N
Battery	X	
Bat. Tray & Holder	X	
Battery Terminals	X	
Wiring Secured	X	
Alternator	X	
Radiator Pressure Test	X	
Radiator	X	
Radiator Hoses	X	
Radiator Reservoir	X	
Coolant Condition	X	
Heater Hoses & Tap	X	
Heater Hoses to Core	X	
A/C Operation	X	
A/C Condenser	X	
A/C Cooling Fan	X	
A/C Pipes and Hoses	X	
A/C Compressor	X	
Thermostat Housing	X	
Cooling/Fan Blade	X	
Water Pump Operation	X	
Drive Belts	X	
Power Steering	X	
Hydraulic Hoses	X	
Fluid Condition	X	

	S	N
Fuel Pump Operation	X	
Fuel Line/Hoses	X	
F.I Assy/Carb	N	A
Air Filter Casing	X	
Welsh Plugs	X	
Distributor	N	A
Starter Motor	X	
Power Booster	X	
Brake Master Cyl	X	
Clutch Master/Cable	X	
Cylinder Cap/Seal	X	
Emission Control Visual	X	
Intake Manifold	X	
Exhaust Manifold	X	
Turbo Charger	N	A
Turbo -oil Leaks	N	A
Engine Cover	X	
Fuse Box & Cover	X	
Washer Bottle	X	
Cables	X	
LPG System	N	A
Oil Cap Deposits	X	
Engine Mounts	X	

# Engine Condition

- Compression Result
- Cold Engine Run
- Hot Engine Run
- CO2 Head Leakage Test
- Engine Exhaust Smoke
- Vehicle Diagnostic Scan
- Engine Oil Level
- Engine Bay Oil Leaks
- Engine Oil Condition
- Automatic Oil Condition

Optional

X		
X		
X		
X		
X		No Codes Detected
X		
X		
X		

Note:

Added Notes:

# Under Body Drive Line

S = Satisfactory/Consistent with Mileage

N = Needs Service/Repair

	S	N
Clutch Slave / Fork	X	
Speedo Drive	X	
Gearbox Linkages	X	
Gearbox Mounts	X	
Drive shafts	X	
Drive shaft Uni Joints	X	
Trans Fluid Leaks	X	
Trans Wiring Lines	X	
Underside Oil Leaks	X	

	S	N
Front CV Boots	N	A
Rear CV Boots	X	
Front Differential	N	A
Front Diff Oil Leaks	N	A
Rear Differential	X	
Rear Diff Oil Leaks	X	
Transfer case Leaks	X	
Engine / Trans Mounts	X	

# Steering, Brakes and Suspension

Exhaust / Catalytic Mufflers	X	
	X	

LPG Tank Guard	N	A
----------------	---	---

## LEFT FRONT

Rim & Tyre		X
Steer. Arms /Tie Rod	X	
Steer / Suspension Bushes	X	
Strut / Shock	X	
Ball Joint	X	
Hub Assembly	X	
Wheel Bearings	X	
Control Arms	X	
Brake Disc Rotor	X	
Brake Pads	X	
Brake Caliper & Hose	X	
Leaf / Coil Springs	X	
Sway Bar Mount	X	

## RIGHT FRONT

Rim & Tyre		X
Steer. Arms /Tie Rod	X	
Steer / Suspension Bushes	X	
Strut / Shock	X	
Ball Joint	X	
Hub Assembly	X	
Wheel Bearings	X	
Control Arms	X	
Brake Disc Rotor	X	
Brake Pads	X	
Brake Caliper & Hose	X	
Leaf / Coil Springs	X	
Sway Bar Mount	X	

## LEFT REAR

Rim & Tyre		X
Suspension Bushes	X	
Leaf / Control Arm	X	
Strut / Shock	X	
Brake Disc Rotor	X	
Brake Pads	X	
Brake Caliper & Hose	X	
Brake Drag	X	
Wheel Bearing	X	

## RIGHT REAR

Rim & Tyre		X
Steer. Arms /Tie Rod	X	
Leaf / Control Arm	X	
Strut / Shock	X	
Brake Disc Rotor	X	
Brake Pads	X	
Brake Caliper & Hose	X	
Brake Drag	X	
Wheel Bearing	X	

Added Notes:

All wheel rims are marked.

# Chassis, Body & Panel

S = Satisfactory/Consistent with Mileage

N = Needs Service/Repair

## RIGHT FRONT

	S	N
Windscreen	X	
Bonnet Stay/Struts	X	
Park/Headlight Glass	X	
Repeater/Indicator Lens	X	
Door Hinges	X	
Door Rubber Seals	X	
Door Lock & Key	X	

## LEFT FRONT

	S	N
Bumper/Bull Bar assy		X
Park/Headlight Glass	X	
Repeater/Indicator Lens	X	
Door hinges	X	
Door Rubber Seals	X	
Door Lock & Key	X	

## RIGHT REAR


Glass/Trim	X	
Weather Seals/Rubber	X	
Boot Tailgate Support	X	
Tail Light Lens	X	
Spare Wheel or Kit	X	
Jack/Tools	X	
Moulds/Strips	X	

## LEFT REAR

Glass/Trim	X	
Weather Seals/Rubber	X	
Sun Roof	N	A
Fuel Cap/Door	X	
Bumper/Beaver Panel	X	
Tail light Lens	X	
Moulds/Strip	X	

Added Notes:

Lower front bar marked.



Note: Please be advised:

Vehicle Safety Certificates Queensland will note larger type damage and previous accident repairs to all vehicles when conducting a full comprehensive inspection.

However smaller shopping size dents, scratches or hail damage will not be noted or guaranteed due to our mobile service and lighting conditions on site. It is the purchaser's responsibility to re-check the inspected vehicle personally before settlement.

Vehicle Safety Certificates Queensland ADVISES ALL PURCHASERS to check with the relevant authorities Australia wide for any type of Write-off history PRIOR TO PURCHASE.

Vehicle Safety Certificates Queensland gives no guarantees on previous repair history nor is the vehicle's Body alignment measured or components removed. A final visual inspection of a vehicle at the point of sale is the responsibility of the purchaser; Vehicle Safety Certificates Queensland cannot be held liable for any dents/damage or condition change after the initial inspection. Please ensure to view/print this report in colour, if unable to do so please contact us for assistance.

# Interior

S = Satisfactory/Consistent with Mileage

N = Needs Service/Repair

	S	N
Floor Covering Carpet	X	
Dash Board	X	
Glove Box	X	
Air Vents	X	
Door Trims	X	
Roof Lining	X	
Sun Visor	X	
Interior Light	X	
Interior Mirror	X	
Exterior Mirrors	X	
Comb Switch	X	
Hazard Switch	X	
Front & Rear Wipers	X	
Washers	X	
A/C Operation	X	
Heater Operation	X	
Fan Speed Control	X	
Air Flow Control	X	
Recycle Control	X	

	S	N
Park Brake Operation	X	
Steering Wheel Grip	X	
Horn	X	
Pedal rubbers	X	
Radio	X	
Console	X	
Sun Roof Operation	N	A
Window Operation	X	
Key / Remote	X	
Front Seat Belts	X	
Rear Seat Belts	X	
Front Seat Operation	X	
Rear Seat Operation	X	
Rear Cover / Parcel Tray	X	
Fuel / Temp Gauges	X	
Warning Lights	X	
A.B.S & S.R.S Lights	X	
Oil Pressure Light	X	

**CD & CASSETTE PLAYERS ARE NOT TESTED**

**Some radio's require a security code for operation, please ensure to obtain that code**

[Added Notes:](#)

# Road Test Reports

Inhibitor switch	N	A
Clutch Operation	X	
Clutch Ride	X	
Brake Sink / Travel	X	
Brakes (ABS)	X	
Brake Shudder	X	
Steering	X	
Road Handling	X	
Steering Vibrations	X	
Steering Wheel Align	X	
Gearbox Synchronesh	X	
Engine Performance	GOOD	
Engine Smoke	GOOD	
Speed Limit when Tested	60	

4x4 High & Low	N	A
Rev. Under Load	X	
Gas Operation	N	A
Speedo	X	
Odometer	X	
Trip Meter	X	
Cruise Control	X	
Turbo Charger	N	A
Front C.V Joints	N	A
Driveshaft Vibrations	X	
Ride & Comfort	X	
Trans Flare / Whine	N/A	
Differential Whine	GOOD	

[Added Notes:](#)

# Inspection Report Summary

## Body Rating:

Early Repair required (Body)  
90%

## Mechanical Rating:

Early Repair required (Mec)  
90%

## Interior Rating:

Early Repair required (Interior)  
90%

## General Overview

**Car has two small dents, lower front bar and wheel gutter rash, this vehicle is in great condition. Their are rubber floor mats over the genuine mats. Log books are up to date.**

\*\* This vehicle has been rated taking into consideration the mileage displayed, the vehicle age and the condition of the vehicle as inspected – The higher rating = better the condition.

All vehicles are inspected as presented, please ensure that you are aware of the vehicles options and features example: Air Bag quantity, Engine specifications, cruise control etc, as this can vary from model to model as an option.

Please ensure to read this report in full including any add notes which may point out any repairs, servicing, faults, problems. Further explanation of the report is made by speaking direct with your inspector, whom will phone you after the inspection or by the end of that working day, if you were not available to take the call please phone the inspector as a verbal explanation of the inspection report is important.

WE STRONGLY SUGGEST; A final visual inspection of a vehicle at the time of settlement, and is the responsibility of the purchaser, Vehicle Safety Certificates Queensland can not be held liable for any dents/damage or mechanical condition change or alterations after the initial inspection.

BEWARE: Always check for a clear title before purchasing a vehicle especially on private sales.  
HISTORY AND P.P.S.R ENCUMBERANCE CHECKS ARE AVAILABLE DIRECTLY FROM Vehicle Safety Certificates Queensland (Charges Apply)

PLEASE NOTE: THIS REPORT IS NOT A ROADWORTHY OR SAFETY CERTIFICATE OF ANY KIND, WHICH MAY BE NEEDED IN VARIOUS STATES FOR REGISTRATION PURPOSES.